



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Application No.: 10/749,715 Confirmation No.: 9216

Applicant(s): Brown, Cecil

Filed: 12/30/2003

Art Unit: 2833

Examiner: Hammond, Brigitte R.

Title: Electrical Connector Having Connector Position
Assurance Member

Attorney Docket No.: 003C.0006.U2 (US)

Customer No.: 29,683

Commissioner For Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Request Under 37 C.F.R. §1.48(c)

Sir:

This is a request under 37 C.F.R. §1.48(c) to correct the inventorship in the above-identified patent application. The original inventorship was stated as:

Cecil Brown.

The correct inventorship is:

Cecil Brown;

William R. Lyons; and

Phillip G. Seminara.

Enclosed are the following:

1. Statement from each person being added as an inventor that the addition is necessitated by amendment of the

6/02/2005 MAHMED1 00000094 10749715

2 FC:1464 130.00 OP

07/08/2005 AKELLEY 00000010 501924 10749715

01 FC:1462 400.00 DA